



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200

D412-742-043
Job Sheet 171619



Part No: D412-742-043

Job Qty: 1 ea

Part Name: Repl. Skidtube Fits LH or RH, High Gear, DART (Apical) Tri-Bag Float Comp.



Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 2/6/18

Job Tracking No:

Due Date: 2/9/18

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: DWG D3391-043 REV J SHEETS 1,2 IPP Rev A 05.10.13 New Issue KJ/JLM IPP Rev 06.02.13 ECN 773 dwg
@ rev.D EC IPP Rev:C 07-05-28 As per Rev F JLM IPP Rev:D 07-12-04 ECN 1072 DD verified by:JLM IPP
Rev:E 08-09-08 ecn 08-510 DD verified by:EC IPP Rev:F 11.11.01 as per DSI9517 REV.B DD verified by:EC
IPP REV:G 16.05.02 AS PER DWG REV.J DD VERF:JLM

Ship Via:

000 834

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea		2/8/18	0.00	0.00	Start Up Container		HL 18-2-13
110	HandFinish	1 pcs		2/9/18	0.00	3.50	HandFinish4		HL 18-2-13
120	QC	1 pcs		2/9/18	0.00	0.00	QC5		38
125	DC	1 pcs		2/9/18	0.00	0.00	DC		9-89
130	Packaging	1 pcs		2/9/18	0.00	0.00	Packaging3-2		Smb
140	QC21-FG	1 Ea		2/9/18	0.00	0.00	QC21		DAS FEB 14 2018

Part Op 110 - 1-Install tubes together and seal them all the way around using Sikaflex 241/291. Ensure tube ends line-up with
Descriptions: saddle holes for proper alignment. using 7/16" "T" Pins. A/R Sikaflex-241/-291 _____ Expiry date: _____
2-Install wearplates as per Dwg D3391. Ensure that plastic washers are against wearplate, then topped
with the SS washer. Seal all bolts with sikaflex except ones with inserts on inside of tube ,hand tighten only bolts with no
sikaflex. A/R Sikaflex-241/-291 _____ Expiry date: _____ 3-Remove "T" pins once sikaflex is dry.
4-Coat all exposed hardware with LPS Procyon. Remove any excess off with MEK degreaser. A/R LPS Procyon

VERIFY FWD AND AFT SADDLE FIT DURING ASSEMBLY BY: _____ DATE: _____
125 - If D412-742-043 is a W/O on it's own, Photocopy bluefile and create labels per PPP D412-742-043 CHG007
130 - Identify and pack for shipping as per PPP D412-742-043 Location: _____ PPP Rev: _____

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
AN3C4A	Bolt	24 Ea (24 ea)	90-Start up Operation	5019394
AN3C6A	Bolt	4 Ea (4 ea)	90-Start up Operation	5019397
AN5C7A	Bolt	10 Ea (10 ea)	90-Start up Operation	5019411
D3391-021	Fwd Tube Assembly	1 pcs (1 ea)	90-Start up Operation	5017240
D3391-023	Mid Tube Assembly	1 Ea (1 ea)	90-Start up Operation	5031089
D3391-025	Aft Tube Assembly	1 pcs (1 ea)	90-Start up Operation	5014180
D4095-041	Wearplate Fwd	1 Ea (1 ea)	90-Start up Operation	5006063
D4095-043	Wearplate Aft	1 Ea (1 ea)	90-Start up Operation	5006064
D4095-045	Wearplate Center	1 Ea (1 ea)	90-Start up Operation	5041025
NAS1149C0332R	Washer	28 Ea (28 ea)	90-Start up Operation	5019380-1
NAS1149C0532R	Washer	10 Ea (10 ea)	90-Start up Operation	5014735

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
-----------	----------------	----------	-----------	-----------

QA Closed: _____ Date: _____

Work Order update only

Work Order: _____		DISPOSITION		AGAINST DEPARTMENT/PROCESS																																																																																																			
Part No. _____		Rework ☐		Skid-tube ☐		Engineering ☐																																																																																																	
NCR No. _____		Scrap ☐		Cross tube ☐		Quality ☐																																																																																																	
Date : _____		Use-as-is ☐		Water let ☐		Other ☐																																																																																																	
Step #: _____		Suspected Unapproved ☐				MRB (QSI042) Approval _____																																																																																																	
Description Work Order Deviation				Completed By _____																																																																																																			
				Lead hand / Supervisor Approval Verification _____																																																																																																			
				QC / QA Coordinator Approval _____																																																																																																			
Root Cause <table border="1"> <tr> <td>Environment</td> <td>☐</td> <td>No Re-verification</td> <td>☐</td> <td>Pressure/Forced</td> <td>☐</td> <td>Te</td> <td>☐</td> </tr> <tr> <td>Design</td> <td>☐</td> <td>Operator</td> <td>☐</td> <td>Bending</td> <td>☐</td> <td>Se</td> <td>☐</td> </tr> <tr> <td>Doc/Data</td> <td>☐</td> <td>Offset/Setup</td> <td>☐</td> <td>Centre Not Concentric</td> <td>☐</td> <td>BC</td> <td>☐</td> </tr> <tr> <td>Equip/Tooling</td> <td>☐</td> <td>Supplier</td> <td>☐</td> <td>Cracks</td> <td>☐</td> <td>Br</td> <td>☐</td> </tr> <tr> <td>Handling/Pre</td> <td>☐</td> <td>Training</td> <td>☐</td> <td>Crimp/Kink/Ripple/Wave</td> <td>☐</td> <td>Ins</td> <td>☐</td> </tr> <tr> <td>Material</td> <td>☐</td> <td>Use for Testing</td> <td>☐</td> <td>Cuffs</td> <td>☐</td> <td>Co</td> <td>☐</td> </tr> <tr> <td>Internal Transport</td> <td>☐</td> <td>Poor Information</td> <td>☐</td> <td>Crushing</td> <td>☐</td> <td>Co</td> <td>☐</td> </tr> <tr> <td>Tribal Knowledge</td> <td>☐</td> <td>Rushing</td> <td>☐</td> <td>Heat Treat</td> <td>☐</td> <td>Cu</td> <td>☐</td> </tr> <tr> <td>LOA</td> <td>☐</td> <td>Product Improvement</td> <td>☐</td> <td>Wave/Twist in Tube</td> <td>☐</td> <td>Ins</td> <td>☐</td> </tr> <tr> <td>Substation</td> <td>☐</td> <td>Process Improvement</td> <td>☐</td> <td>Marks/Chatter</td> <td>☐</td> <td>Dri</td> <td>☐</td> </tr> <tr> <td>Past Expiry Date</td> <td>☐</td> <td>Manufacturing Process</td> <td>☐</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Misidentified</td> <td>☐</td> <td>Past Due</td> <td>☐</td> <td>OTHER :</td> <td></td> <td></td> <td></td> </tr> </table>				Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Te	☐	Design	☐	Operator	☐	Bending	☐	Se	☐	Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BC	☐	Equip/Tooling	☐	Supplier	☐	Cracks	☐	Br	☐	Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Ins	☐	Material	☐	Use for Testing	☐	Cuffs	☐	Co	☐	Internal Transport	☐	Poor Information	☐	Crushing	☐	Co	☐	Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cu	☐	LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Ins	☐	Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Dri	☐	Past Expiry Date	☐	Manufacturing Process	☐					Misidentified	☐	Past Due	☐	OTHER :				Dart Aerospace Ltd. 1270 Aberdeen Street Hawkesbury, ON K64 1K7 CANADA TEL.: 1 613 632-5200 Email: sales@dartaero.com www.dartaerospace.com DART AEROSPACE S041820 Repl. Skidtube Fits LH or RH, High Gear, DART (Apical) Tri - Bag Float Comp. PART NO: D412-742-043 Original Serial #: S041820 Revision: Operation: Change No: Start up Operation 02/13/18 CHG007 Job No: 171619			
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Te	☐																																																																																																
Design	☐	Operator	☐	Bending	☐	Se	☐																																																																																																
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BC	☐																																																																																																
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Br	☐																																																																																																
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Ins	☐																																																																																																
Material	☐	Use for Testing	☐	Cuffs	☐	Co	☐																																																																																																
Internal Transport	☐	Poor Information	☐	Crushing	☐	Co	☐																																																																																																
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cu	☐																																																																																																
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Ins	☐																																																																																																
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Dri	☐																																																																																																
Past Expiry Date	☐	Manufacturing Process	☐																																																																																																				
Misidentified	☐	Past Due	☐	OTHER :																																																																																																			